




Spare parts drawing - list

Modelnumber: SW1E355101

EU / 20V - "BRUSHLESS MOTOR" Cordless circular saw



Pos.	Spare part number	Description	QTY
1	2850007001	Clamping Flange Parts Set	1
2	2850888001	Lower guard Parts Set	1
3	2850883001	Lamp Cover Parts Set	1
4	2850891001	Lamp Parts Set	1
5	2829716001	Switch Trigger Parts Set	1
6	2829715001	Button Parts Set	1
7	2850886001	Housing Parts Set	1
8	2850951001	Field 20V Parts Set	1
9	2751594001	Armature 20V	1
10	2829710001	Locking Pin Parts Set	1
11	2790741001	Bearing Plate	1
12	2850890001	Upper guard Parts Set	1
13	2850884001	Vacuum Adapter	1
14	2850889001	Spindle Parts Set	1
15	2826143001	Parallel-Guide	1
16	2850885001	Base Plate Parts Set	1

17	2850887001	Bolt Parts Set	1
18	2831816001	Switch Parts Set	1
19A	BR1E310701	Battery 20V MAX 2,0Ah (Keepcool) Li-ion	1
19B	BR1E313001	Battery 20V MAX 2,0Ah (Keepcool) Li-ion with USB	1
19C	BR1E310201	Battery 20V MAX 2,5Ah (Keepcool) Li-ion	1
19D	BR1E310401	Battery 20V MAX 4,0Ah (Keepcool) Li-ion	1
19E	BR1E310501	Battery 20V MAX 5,0Ah (Keepcool) Li-ion	1
20A	CR1E312901	Charger EU 230V/20V 1,0A	1
20B	CR1E312201	Charger EU 230V/20V 2,4A	1
20C	CR1E312801	Dual charger EU 230V/20V 2x2,4A	1
20D	CR1E312301	Charger EU 230V/20V 6,0A	1
20E	CR1E313201	Dual charger EU 230V/20V 2x6,0A	1
20F	CR1U312203	Charger UK 230V/20V 2,4A	1
20G	CR1U312803	Dual charger UK 230V/20V 2x2,4A	1
20H	CR1U312303	Charger UK 230V/20V 6,0A	1