




Spare parts drawing - list

Modelnumber: SW1E354001

EU / 20V - "BRUSHLESS MOTOR" cordless circular saw

SKIL
SW1E 3540 01

Stand } 2022-10-24 Fig./Abb. 1
Issue }



Änderungen vorbehalten
Modifications reserved
Modifications réservées
Salvo modificaciones

Pos.	Spare part number	Description	QTY
1	2829051001	Clamping Flange Parts Set	1
2	2828883001	Lower guard Parts Set	1
3	2829300001	Upper guard Parts Set	1
4	3133500001	Vacuum Adapter	1
5	2829299001	Locking Pin Parts Set	1
6	2829296001	Spindle Parts Set	1
7	2751457001	Armature 20V	1
8	2831242001	Lamp	1
9	2829295001	Switch & Field 20V Parts Set	1
10	2829298001	Housing Parts Set	1
11	2829297001	Base Plate Parts Set	1
12	2826143001	Parallel-Guide	1
13A	BR1E310701	Battery 20V MAX 2,0Ah (Keepcool) Li-ion	1
13B	BR1E313001	Battery 20V MAX 2,0Ah (Keepcool) Li-ion with USB	1
13C	BR1E310201	Battery 20V MAX 2,5Ah (Keepcool) Li-ion	1
13D	BR1E310401	Battery 20V MAX 4,0Ah (Keepcool) Li-ion	1
13E	BR1E310501	Battery 20V MAX 5,0Ah (Keepcool) Li-ion	1

14A	CR1E312901	Charger EU 230V/20V 1,0A	1
14B	CR1E312201	Charger EU 230V/20V 2,4A	1
14C	CR1E312801	Dual charger EU 230V/20V 2x2,4A	1
14D	CR1E312301	Charger EU 230V/20V 6,0A	1
14E	CR1U312203	Charger UK 230V/20V 2,4A	1
14F	CR1U312803	Dual charger UK 230V/20V 2x2,4A	1
14G	CR1U312303	Charger UK 230V/20V 6,0A	1