



Spare parts drawing - list


Modelnumber: SR1E375101

EU / 20V - "BRUSHLESS MOTOR" Cordless random orbit sander

SKIL
SR1E375101

Stand }
Issue } 24-03-13

Fig. / Abb. 1



Änderungen vorbehalten
Modifications reserved
Modifications réservées
Salvo modificaciones

Pos.	Spare part number	Description	QTY
1	2832247001	Switch Parts Set	1
2	2851583001	Housing Parts Set	1
3	2740751001	Field 20V Parts Set	1
4	2751671001	Armature 20V	1
5	2851585001	Vacuum Adapter Parts Set	1
6	5690439001	Brake Ring	1
7	2829947001	Backing Pad Parts Set	1
8	3129734001	Vacuum Adapter	1
9	2851015001	Dust container	1
10	2851014001	Dust Bag	1
11A	BR1E310701	Battery 20V MAX 2,0Ah (Keepcool) Li-ion	1
11B	BR1E313001	Battery 20V MAX 2,0Ah (Keepcool) Li-ion with USB	1
11C	BR1E310201	Battery 20V MAX 2,5Ah (Keepcool) Li-ion	1
11D	BR1E310401	Battery 20V MAX 4,0Ah (Keepcool) Li-ion	1
11E	BR1E310501	Battery 20V MAX 5,0Ah (Keepcool) Li-ion	1
12A	CR1E312901	Charger EU 230V/20V 1,0A	1
12B	CR1E312201	Charger EU 230V/20V 2,4A	1
12C	CR1E312801	Dual charger EU 230V/20V 2x2,4A	1
12D	CR1E312301	Charger EU 230V/20V 6,0A	1

12E	CR1E313201	Dual charger EU 230V/20V 2x6,0A	1
12F	CR1U312203	Charger UK 230V/20V 2,4A	1
12G	CR1U312803	Dual charger UK 230V/20V 2x2,4A	1
12H	CR1U312303	Charger UK 230V/20V 6,0A	1