



Spare parts drawing - list


Modelnumber: RH1E385101

EU / 20V - "BRUSHLESS MOTOR" cordless rotary hammer

SKIL
RH1E 3851 01

Stand
Issue 22-07-12

Fig. / Abb. 1



Pos.	Spare part number	Description	QTY
1	2828839001	Wobble Plate Parts Set	1
2	2828838001	Drive Shaft	1
3	2829436001	Switch Parts Set	1
4	2829428001	Auxiliary Handle	1
5	2829429001	SDS+ Parts Set	1
6	2829431001	Change-Over Switch	1
7	2740657001	Field 20V	1
8	2829434001	Hammer Piston Parts Set	1
9	2829432001	Rotary Knob Parts Set	1
10	2829433001	Armature 20V	1
11	2829430001	Housing Parts Set	1
12	2829435001	Base Frame Parts Set	1
13A	BR1E310701	Battery 20V MAX 2,0Ah (Keepcool) Li-ion	1
13B	BR1E313001	Battery 20V MAX 2,0Ah (Keepcool) Li-ion with USB	1
13C	BR1E310201	Battery 20V MAX 2,5Ah (Keepcool) Li-ion	1
13D	BR1E310401	Battery 20V MAX 4,0Ah (Keepcool) Li-ion	1

13E	BR1E310501	Battery 20V MAX 5,0Ah (Keepcool) Li-ion	1
14A	CR1E312401	Charger EU 230V/20V 0,4A	1
14B	CR1E312201	Charger EU 230V/20V 2,4A	1
14C	CR1E312801	Dual charger EU 230V/20V 2x2,4A	1
14D	CR1E312301	Charger EU 230V/20V 6,0A	1