



Spare parts drawing - list


Modelnumber: SW1E357201

EU / 20V - "BRUSHLESS MOTOR" Cordless circular saw

SKIL
SW1E 3572 01

Stand
Issue } 22-10-27

Fig. /Abb. 1



Änderungen vorbehalten
Modifications reserved
Modifications réservées
Salvo modificaciones

20A 2,0Ah
20B 2,0Ah with USB
20C 2,5Ah
20D 4,0Ah
20E 5,0Ah

21A 1,0A/ EU/ 230V
21B 2,4A/ EU/ 230V
21C 2X2,4A/ EU/ 230V
21D 6,0A/ EU/ 230V
21E 2X6,0A/ EU/ 230V
21F 2,4A/ UK/ 230V
21G 2X2,4A/ UK/ 230V
21H 6,0A/ UK/ 230V

Pos.	Spare part number	Description	QTY
1	2828708001	Clamping Flange Parts Set	1
2	2828725001	Lower guard Parts Set	1
3	2829731001	Spindle Parts Set	1
4	2829726001	Locking Pin Parts Set	1
5	2829734001	Upper guard Parts Set	1
6	2829738001	Auxiliary Handle	1
7	2829733001	Electronic Module Parts Set	1
8	4870740001	Switch Parts Set	1
9	2829739001	Button Parts Set	1
10	2824191001	Hook	1
11	3134086001	Vacuum Adapter	1
12	2829732001	Housing Parts Set	1
13	2829740001	Motor Housing Parts Set	1
14	2740685001	Field 20V Parts Set	1
15	2751536001	Armature 20V Parts Set	1
16	2829737001	Bolt Parts Set	1
17	2829736001	Base Plate Parts Set	1
18	5680232001	Adjusting Wrench	1

19	2823929001	Parallel-Guide	1
19A	BR1E310701	Battery 20V MAX 2,0Ah (Keepcool) Li-ion	1
19B	BR1E313001	Battery 20V MAX 2,0Ah (Keepcool) Li-ion with USB	1
19C	BR1E310201	Battery 20V MAX 2,5Ah (Keepcool) Li-ion	1
19D	BR1E310401	Battery 20V MAX 4,0Ah (Keepcool) Li-ion	1
19E	BR1E310501	Battery 20V MAX 5,0Ah (Keepcool) Li-ion	1
20A	CR1E312901	Charger EU 230V/20V 1,0A	1
20B	CR1E312201	Charger EU 230V/20V 2,4A	1
20C	CR1E312801	Dual charger EU 230V/20V 2x2,4A	1
20D	CR1E312301	Charger EU 230V/20V 6,0A	1
20E	CR1E313201	Dual charger EU 230V/20V 2x6,0A	1
20F	CR1U312203	Charger UK 230V/20V 2,4A	1
20G	CR1U312803	Dual charger UK 230V/20V 2x2,4A	1
20H	CR1U312303	Charger UK 230V/20V 6,0A	1