




Spare parts drawing - list

Modelnumber: SR1E372001

EU / 20V - "BRUSHLESS MOTOR" cordless MULTI SANDER

SKIL
SR1E 3720 01

Stand } 2022-10-24 Fig. /Abb. 1
Issue }



Pos.	Spare part number	Description	QTY
1	2828760001	Housing Parts Set	1
2	2828761001	Swivel Element Parts Set	1
3	2751439001	Armature 20V	1
4	2825153001	Switch & Field 20V Parts Set	1
5	2823962002	Spindle Parts Set	1
6	2823717001	Base Plate Parts Set	1
7	2828514001	Dust container	1
8	2823899001	Sander Plate	1
9	2828411001	Louvre attachment	1
10	2828412001	Finger attachment	1
11	2828410001	Flexible sanding attachment	1
12A	BR1E310701	Battery 20V MAX 2,0Ah (Keepcool) Li-ion	1
12B	BR1E313001	Battery 20V MAX 2,0Ah (Keepcool) Li-ion with USB	1
12C	BR1E310201	Battery 20V MAX 2,5Ah (Keepcool) Li-ion	1
12D	BR1E310401	Battery 20V MAX 4,0Ah (Keepcool) Li-ion	1
12E	BR1E310501	Battery 20V MAX 5,0Ah (Keepcool) Li-ion	1
13A	CR1E312401	Charger EU 230V/20V 0,4A	1
13B	CR1E312901	Charger EU 230V/20V 1,0A	1
13C	CR1E312201	Charger EU 230V/20V 2,4A	1

13D	CR1E312801	Dual charger EU 230V/20V 2x2,4A	1
13E	CR1E312301	Charger EU 230V/20V 6,0A	1
13F	CR1U312203	Charger UK 230V/20V 2,4A	1
13G	CR1U312803	Dual charger UK 230V/20V 2x2,4A	1
13H	CR1U312303	Charger UK 230V/20V 6,0A	1