




Spare parts drawing - list

Modelnumber: MF1E362201

EU / 20V - BRUSHLESS MOTOR" cordless multi- function tool

SKIL
MF1E362201

Stand
Issue } 24-04-23 Fig. /Abb. 1



Pos.	Spare part number	Description	QTY
1	2832277001	Switch Parts Set	1
2	3130468001	Actuator	1
3	2851640001	Gear Housing Parts Set	1
4	2740754001	Field 20V Parts Set	1
5	2751659001	Armature 20V	1
6	2851403001	Adjusting Lever Parts Set	1
7	2851641001	Housing Parts Set	1
8	2851639001	Spindle Parts Set	1
9	3556102001	Linkage part	1
10	2826109001	Depth gauge	1
11	2823580002	Sander Plate	1
12A	BR1E310701	Battery 20V MAX 2,0Ah (Keepcool) Li-ion	1
12B	BR1E313001	Battery 20V MAX 2,0Ah (Keepcool) Li-ion with USB	1
12C	BR1E310201	Battery 20V MAX 2,5Ah (Keepcool) Li-ion	1
12D	BR1E310401	Battery 20V MAX 4,0Ah (Keepcool) Li-ion	1
12E	BR1E310501	Battery 20V MAX 5,0Ah (Keepcool) Li-ion	1
13A	CR1E312901	Charger EU 230V/20V 1,0A	1
13B	CR1E312201	Charger EU 230V/20V 2,4A	1
13C	CR1E312801	Dual charger EU 230V/20V 2x2,4A	1

13D	CR1E312301	Charger EU 230V/20V 6,0A	1
13E	CR1E313201	Dual charger EU 230V/20V 2x6,0A	1
13F	CR1U312203	Charger UK 230V/20V 2,4A	1
13G	CR1U312803	Dual charger UK 230V/20V 2x2,4A	1
13H	CR1U312303	Charger UK 230V/20V 6,0A	1